

R100, R104, R105

Резцы с внутренним подводом СОЖ Boring cutters with internal coolant supply

Код / Code	Рис./ Pic.	D	d _{min}	L	L ₁	L ₂	Винт/ Screw	Ключ/ Key	Пластина/ Insert	Кг/ Kg
R104.12/06-WC02	1	12	6	56	21	22	SR14-299	T-6/5	WCGT 0201...	0,03
R104.12/08-WC02	1	12	8	61	28	22	SR14-299	T-6/5	WCGT 0201...	0,04
R100.12/10-CC06	2	12	10	66	35	22	SR14-548	T-7/5	CC...0602...	0,03
R100.12/12-CC06	2	12	12	72	42	22	SR14-548	T-7/5	CC...0602...	0,04
R100.12/14-CC06	2	12	14	77	50	22	SR14-548	T-7/5	CC...0602...	0,05
R100.12/16-CC06	3	12	16	82	60	-	SR14-548	T-7/5	CC...0602...	0,06
R100.12/18-CC06	3	12	18	82	60	-	SR14-548	T-7/5	CC...0602...	0,06
R100.12/21-CC09	4	12	21	87	-	22	SR16-236	T-15/5	CC...09T3...	0,10
R100.12/25-CC09	4	12	25	87	-	22	SR16-236	T-15/5	CC...09T3...	0,10
R105.12/10-TP09	2	12	10	66	35	22	SR14-298	T-8/5	TP...0902...	0,03
R105.12/12-TP09	2	12	12	72	42	22	SR14-298	T-8/5	TP...0902...	0,04
R105.12/14-TP09	2	12	14	77	50	22	SR14-298	T-8/5	TP...0902...	0,05
R105.12/16-TP09	3	12	16	82	60	-	SR14-298	T-8/5	TP...0902...	0,06
R105.12/18-TP11	3	12	18	82	60	-	SR14-300	T-8/5	TP...1103...	0,06
R105.12/21-TP11	4	12	21	87	-	22	SR14-300	T-8/5	TP...1103...	0,10
R105.12/25-TP11	4	12	25	87	-	22	SR14-300	T-8/5	TP...1103...	0,10
R104.16/06-WC02	1	16	6	70	21	30	SR14-299	T-6/5	WCGT 0201...	0,06
R104.16/08-WC02	1	16	8	75	28	30	SR14-299	T-6/5	WCGT 0201...	0,07
R100.16/10-CC06	2	16	10	80	35	30	SR14-548	T-7/5	CC...0602...	0,07
R100.16/12-CC06	2	16	12	85	42	30	SR14-548	T-7/5	CC...0602...	0,08
R100.16/14-CC06	2	16	14	90	50	30	SR14-548	T-7/5	CC...0602...	0,09
R100.16/16-CC06	2	16	16	95	59	30	SR14-548	T-7/5	CC...0602...	0,10
R100.16/18-CC06	2	16	18	100	69	30	SR14-548	T-7/5	CC...0602...	0,13
R100.16/22-CC09	3	16	22	100	70	-	SR16-236	T-15/5	CC...09T3...	0,15
R100.16/28-CC09	3	16	28	100	70	-	SR16-236	T-15/5	CC...09T3...	0,14
R105.16/10-TP09	2	16	10	80	35	30	SR14-298	T-8/5	TP...0902...	0,06
R105.16/12-TP09	2	16	12	85	42	30	SR14-298	T-8/5	TP...0902...	0,09
R105.16/14-TP09	2	16	14	90	50	30	SR14-298	T-8/5	TP...0902...	0,09
R105.16/16-TP09	2	16	16	95	60	30	SR14-298	T-8/5	TP...0902...	0,10
R105.16/18-TP11	2	16	18	100	69	30	SR14-300	T-8/5	TP...1103...	0,12
R105.16/22-TP11	3	16	22	100	70	-	SR14-300	T-8/5	TP...1103...	0,13
R105.16/28-TP11	3	16	28	100	70	-	SR14-300	T-8/5	TP...1103...	0,16

